



## FIGURES










MEMPHIS ENVIRONMENTAL CENTER, INC.

5909 Shelby Oaks Drive, Suite 146  
Memphis, Tennessee 38134



**FIGURE 3-1**  
**DIELDRIN DISTRIBUTION ALONG NORTH BANK**  
**OF CYPRESS CREEK CHANNEL**




Notes:  
 A is within construction easement  
 B is outside of construction easement  
 C is remote from Creek and not related to construction easement  
 Open marker denotes non-detect concentration  
 All results reported on a dry weight basis

MEMPHIS ENVIRONMENTAL CENTER, INC.

5909 Shelby Oaks Drive, Suite 146  
 Memphis, Tennessee 38134




**FIGURE 3-2**  
**DIELDRIN DISTRIBUTION ALONG SOUTH BANK**  
**OF CYPRESS CREEK CHANNEL**



MEMPHIS ENVIRONMENTAL CENTER, INC.

5909 Shelby Oaks Drive, Suite 146  
Memphis, Tennessee 38134



**FIGURE 3-3**  
**DIELDRIN DISTRIBUTION BY CONCENTRATION RANKING**